# DailyLogsPro - Sample Construction Daily Log

Project:	Downtown Office Renovation	Project No.:	DL-24018
Owner:	Metro Property Group	GC:	ABC Contracting LLC
Address:	123 Main Street, Detroit, MI		

Date:	Dec 26, 2025	Prepared By:	J. Superintendent
Location:	Level 2 – East Wing	Weather:	Rain AM, Clear PM
Hours:	7:00 AM – 3:30 PM	Crew:	8 Total

#### Work Performed

Installed metal studs in Rooms 210–218. Began electrical and low-voltage rough-in. Interior cleanup and material staging completed after weather delay.

#### Crew on Site

6 carpenters, 2 electricians

### Delays / Issues

Heavy rain from 7:15–10:30 AM caused standing water at so this cess road. Exterior work suspended ~3 hours. No safety incidents.

### Deliveries / Inspections

Lighting fixtures delivered and stored in Roor 105.. 'o inspections today.

## **Photos Attached**

- Level 2 framing progress
- · Standing water at south access road
- Material staging area

SAMPLE - Generated by DailyLogsPro. Final product includes geo/time verification and photo metadata.